Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"20060247872"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 17:37
S1	1	11/038709	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 00:04
S2	373	performance with collect\$4 same compensat\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 00:51
53	1	performance with collect\$4 same compensat\$4 same calibration with (program software algorithm)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 00:06
S4	2	"713"/\$.ccls. and performance with collect\$4 same compensat\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 00:07
S5	8	"5939625"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 01:45
S6	1	10/539128	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 00:57

S7	2	"20050038632"	US-PGPUB;	OR	OFF	2007/12/23 01:49
			USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB			
S8	19	"6574537"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/12/23 11:00
S9	3573	(plane vehicle aircraft car)and (fault\$4 error\$4) with (sensor\$3 actuator\$3)near5 (sens\$4 measur\$4 detect\$4) same (diagnosis determin\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 11:11
S10	1	S9 and map\$4 same list same error\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 11:17
S11	0	("2007/0067678").URPN.	USPAT	OR	OFF	2007/12/23 11:16
S12	4	hosek.in. and fault	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/12/23 11:24
S13	10389	(health fault) and vehicle .ti.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 11:25
S14	1573	S13 and (sensor\$4 actuator\$3) and memory	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/12/23 11:26

S15	260	S14 and map\$4 and diagnos\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 11:40
S16	111	10/090330 09/706943 "6353785" "6161071"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/12/23 11:40
S17	5	S15 AND S16	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:34
S18	21	"6161071" and warning same sens\$4 and fault\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:39
S19	7	"6161071" and warning same sens\$4 and fault\$4 and actuator\$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:43
S20	474	fault with (sensor actuator) and list and diagnosis	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:44
S21	387	fault with (sensor actuator) and list and diagnosis and memory	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:44

			· · · · · · · · · · · · · · · · · · ·	T		
S22	166	fault with (sensor actuator) and list and diagnosis and memory and vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 12:45
S23	16	fault with (sensor and actuator) and list and diagnosis and memory and vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 13:32
S24	0	fault with (sensor and actuator) and list and diagnosis and memory and vehicle and propogation	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 13:32
S25	0	(fault\$3 error) with (sensor and actuator) and list and diagnosis and memory and vehicle and propogation	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 13:32
S26	0.	"701"/\$.ccls. and (fault\$3 error) with (sensor and actuator) and list and diagnosis and memory and vehicle and propogation	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:10
S27	353	"701"/\$.ccls. and (fault\$3 error) with (sensor and actuator)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:10
S28	24	"701"/\$.ccls. and (fault\$3 error) with code with (sensor and actuator)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:11

S29	12	"701"/\$.ccls. and (fault\$3 error) with code with (sensor and actuator) same diagnos\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:11
S30	18	"701"/\$.ccls. and (fault\$3 error) with (code value) with (sensor and actuator) same diagnos\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:17
S31	44	"701"/\$.ccls. and (fault\$3 error) with (code value) same (sensor and actuator) same diagnos\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:17
S32	18	"701"/\$.ccls. and (fault\$3 error) with (code value) same (sensor and actuator) same diagnos\$4 same (record\$4 stor\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:20
S33	15	(fault\$3 error) with (code value) with(sensor and actuator) same diagnos\$4 same (record\$4 stor\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 15:25
S34	8	"1573412"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/12/23 17:37

12/23/2007 6:20:19 PM C:\Documents and Settings\abhat\My Documents\EAST\Workspaces\10539128.wsp Page 5